
Form MR-LMO Lynn Springs Quarry (M/003/025), USFS File Code 2810



CONTENTS

	TEXT	PAGES
INFORMATI	ONAL REQUIREMENTS AND RESPONSES	1 TO 14
	ILLUSTRATIONS	FOLLOWING PG.
FIGURE 1	LARGE MINE PERMIT, UGS	1
FIGURE 2	BLM, SURFACE MANAGEMENT STATUS	1
FIGURE 3	BLM, MINERAL STATUS	2
FIGURE 4	CROSS-SECTIONS-OPERATING SITES	4
FIGURE 5	QUARTZITE "QUICK FACTS" & MAP	4
FIGURE 6	BOX ELDER CO., CLASS 'D' ROADS	4
FIGURE 7	SCS SOIL SURVEY MAP	10
FIGURE 8	BOX ELDER CO., IMPORTANT FARMLANDS	8
FIGURE A	PHOTOS, ACCESS ROADS	9
FIGURE B-C	PHOTOS, NORTH QUARRY	9
FIGURE D	PHOTOS, CENTRAL WORK & WASTE ROCK	9
FIGURE E	PHOTOS, SOUTH QUARRY	9
FIGURE 9	GEOLOGIC RESOURCES & MAP	10
FIGURE 10	STRATIGRAPHIC ROCK SECTION	10
FIGURE 11	MULTI-PURPOSE USE MAP	11
FIGURE 12	RECOMMENDED REVEGETATION SPECIES	12
	MAPS	
MAP 1	BASE MAP, USGS TOPOGRAPHIC	2
MAP 2	SURFACE FACILLITIES, QUARRY AREA	POCKET
MAP 3	SURFACE FACILLITIES, MILL SITE	POCKET
MAP 4	CLARKS BASIN FM. QUARTZITE	6
	ATTACHMENTS	
1	SCS, SOIL & VEGETATION	10
2	SURETY VARIANCE	14
•	TABLES	
1	SCHEDULE OF OPERATIONS & RECLAIM. SITES	4
2	WATER-BEARING PROPERTIES OF ROCK UNITS	5
	APPENDIX	
HYDROLOGIC RECON. OF GROUSE CREEK VALLEY, 1970		

HYDROLOGIC RECON. OF GROUSE CREEK VALLEY, 1970 SOIL SURVEY OF BOX ELDER CO., WEST. PART, SEPT. 1997 DIVISION'S PLAN REVIEW OF MARCH 11, 1996